



Supersonic Particle Deposition for Repair and Corrosion Protection of Mg Gearboxes

ASETSDefense Work Shop Sept. 2, 2009

Brian M. Gabriel, Phillip F. Leyman, Dennis J. Helfritch, and Victor K. Champagne* ARL Center for Cold Spray

Brian M. Gabriel
Army Research Laboratory
RDRL-WMM-C
Building 4600, Deer Creek Loop
APG, MD 21005
Phone: (410) 306-2719
Fax: (410) 306-0829

brian.m.gabriel@arl.army.mil

*Program Manager and POC for ARL Center for Cold Spray







After

| maintaining the data needed, and c including suggestions for reducing | lection of information is estimated to completing and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding ar DMB control number. | ion of information. Send comments arters Services, Directorate for Info | s regarding this burden estimate or formation Operations and Reports | or any other aspect of the property of the contract of the con | nis collection of information, Highway, Suite 1204, Arlington |
|--|--|--|---|--|--|
| 1. REPORT DATE 02 SEP 2009 | | 2. REPORT TYPE | | 3. DATES COVE 00-00-2009 | red To 00-00-2009 |
| 4. TITLE AND SUBTITLE | | | | 5a. CONTRACT NUMBER | |
| Supersonic Particle Deposition for Repair and Corrosion Protection of | | | Protection of | 5b. GRANT NUMBER | |
| Mg Gearboxes | | | | 5c. PROGRAM ELEMENT NUMBER | |
| 6. AUTHOR(S) | | | 5d. PROJECT NUMBER | | |
| | | | | 5e. TASK NUMBER | |
| | | | | 5f. WORK UNIT NUMBER | |
| 7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U. S. Army Research Laboratory,RDRL-WMM-C,Building 4600, Deer Creek Loop,Aberdeen Proving Ground,MD,21005 8. PERFORMING ORGANIZATION REPORT NUMBER | | | | | |
| 9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) | | | 10. SPONSOR/MONITOR'S ACRONYM(S) | | |
| | | | 11. SPONSOR/MONITOR'S REPORT NUMBER(S) | | |
| 12. DISTRIBUTION/AVAIL Approved for publ | LABILITY STATEMENT ic release; distributi | on unlimited | | | |
| | OTES 99: Sustainable Surf , Westminster, CO. | | - | Defense Worl | kshop, August 31 - |
| 14. ABSTRACT | | | | | |
| 15. SUBJECT TERMS | | | | | |
| 16. SECURITY CLASSIFICATION OF: 17. LIMITATION OF 18. NUMBER 19a. NAME OF | | | | | |
| a. REPORT unclassified | b. ABSTRACT unclassified | c. THIS PAGE unclassified | Same as Report (SAR) | OF PAGES 33 | RESPONSIBLE PERSON |

Report Documentation Page

Form Approved OMB No. 0704-0188



Core Team Members



- Victor Champagne- Program Manager Cold Spray Center Primary Contact, Army Research Laboratory, Aberdeen Proving Ground, MD, 410-306-0822, vchampag@arl.army.mil
- ➤ Robert Kestler, NADEP-CP, Cherry Point, NC 252-464-9888 robert.kestler@navy.mil
- ➤ **Robert Guillemette**, Sikorsky Aircraft, Stratford, CT 203-386-7559 rguillemette@sikorsky.com
- ➤ **George Liu**, Army Aviation Missile Command, Huntsville, AL, 256-313-8762, george.g.liu@us.army.mil
- > **Timothy J. Eden**, Applied Research Laboratory, The Pennsylvania State University, State College, PA, 814-865-5880, tje1@email.psu.edu
- ➤ Darren Gerrard, DSTO, Australia 61-396-267957 darren.gerrard@dsto.defence.gov.au
- Stacey Luker, JSF ESOH, Cherry Point, NC 252-444-2034 stacey.luker@wylelabs.com
- ➤ **Keith Legg**, Rowan Technology Group, Libertyville, IL 847-680-9420 klegg@rowantechnology.com



ARL Center for Cold Spray Team






TECHNICAL OBJECTIVES



> Demonstrate and qualify SPD aluminum alloy coatings as a cost-effective, ESOH-acceptable technology to provide surface protection and a repair/rebuild methodology for Mg alloy components on Army and Navy helicopters and advanced fixed-wing aircraft such as the Joint Strike Fighter

ARL Center for Cold Spray



Enhancing the Performance of Materials and Components




Technical Approach



Cold Spray/SPD Process

Cold spray, involves the introduction of a heated high-pressure gas such as He or N_2 together with 1 to 50 µm diameter particles of a metal, ceramic and/or polymer into a gun fitted with a De Laval rocket nozzle designed such that the particles exit at supersonic velocities ranging from 400 to 1500 meters-per-second and consolidate upon impacting a suitable surface to form a coating or free-standing structure.

- •Gas temperature range from R.T. to 800°C
- •No melting of particles
- •Negligible oxidation
- •No decomposition or phase changes of deposited particles





SPD Depot overhaul CH-53 gearboxes





- >SPD has little or no impact on repair cost
- >Most of cost is setup actual process cost is small (same as glue shims)
- ➤ Payback of capital and implementation cost is 15 yrs with CH-53 only

 Depends on performance reduced repair or condemnation

 Faster payback over all FRC workload

CH-53 only $\pm 2\sigma$









UH-60 sump flange repair





| | SPD | HVOF |
|-------------------------|------------|----------|
| Setup/maintenance labor | \$392.50 | \$392.50 |
| Run labor | \$3.74 | • |
| Run powder | \$9.71 | \$11.38 |
| Run gas | \$4.29 | \$6.49 |
| Run electricity | \$0.04 | \$0.00 |
| Total cos | t \$410.28 | \$413.01 |
| Run cos | t \$17.78 | \$20.51 |

No cost impact (both processes vendorsupplied)








RDECOM UH-60 Sump Flange Repair



> Problem is that HVOF does not really work Therefore SPD saves condemnation >85 gearboxes/year ■\$11k ea to replace \$1k ea to repair > Cost analysis includes equipment installation and adoption cost >Larger cost savings with more expensive gearbox housings



| | -2 sigma | Value | +2 sigma |
|----------------|-------------|-------------|-------------|
| 15 yr NPV | \$8,682,158 | \$9,229,033 | \$9,775,908 |
| IRR | 145% | 111% | 91% |
| ROI | 82% | 111% | 140% |
| Payback period | 1.2 | 0.0 | 0.0 |



Sump Cost Recovery



UH-60 Sump Assembly Main Module-Main Gearbox Repair



Substrates: ZE41A & AZ91C Magnesium Coating Material: CP-Aluminum and/or 6061 Al

Part Numbers: 70351-48141-041 70351-08141-047

- •Cost of new component \$11,000.00 DLA (Defense Logistics Agency)
- •85 sumps need repair per year based on a Sikorsky study over the last 3 years
 - •Total Replacement Cost Savings estimated to be \$935,000.00/year



Coatings and Substrates



Substrate Materials

| Material | Heat Treat (tens. strength) | Notes |
|----------|-----------------------------------|-----------------|
| AZ91C-T6 | 34 ksi | Legacy systems |
| ZE41A-T5 | 29 ksi | Legacy systems |
| EV31-T6 | 36 ksi | New CH-53, AAAV |



RR Moore with 6061 SPD Coating

Candidate Coating Materials


- Commercially Pure Al-Hardness similar to ZE41A (60 to 70 VHN), Good general corrosion resistance. Candidate for non-structural coatings
- High Purity Al- Best Galvanic compatibility with Mg alloys but at a cost of lower hardness (50 VHN)
- ➤ 6061 aluminum alloy: 90 to 110 VHN, good general corrosion resistance, future candidate for more structural or load bearing coatings.



Galvanic Corrosion



Galvanic Corrosion - Al-Mg Couple



Cathode slightly larger than anode



TECHNICAL APPROACH



Full JTP Qualification Plan


Mechanical Tests

- Adhesion Tensile Bond Test (ASTM C633)
- > Almen Strips
- Flat Tensile Specimens
- > R.R. Moore RB Fatigue
 - surface finished 125RA
- Fretting Fatigue UTRC
- ➤ Impact ASTM D5420
- Hardness
- Porosity
- ROSAN Insert Test
- Triple Lug Shear

- 1. 6061 Aluminum Alloy (He carrier gas)
- 2. HP-Al Bond Coat/CP-Al (N₂ carrier gas)

Corrosion Tests

- Un-scribed ASTM B117
- Scribed ASTM B117
- GM9540 Scribed
- **➤** Galvanic Corrosion (G71)
- Crevice Corrosion (G78)
- **Beach Corrosion**
- **▶ G85** Annex 4-SO₂



UTRC Fretting Fatigue Specimen

Sump Repair Qualification Plan



Substrates: ZE41A & AZ91C Magnesium Allovs

Coating Material:

1.1. 6061 Aluminum Alloy (He carrier gas)

2.HP-Al Bond Coat/CP-Al (N2 carrier gas)

- ➤ Porosity < 1%
- > Almen Strips
- Adhesion Tensile Bond Strength Test
- Unscribed ASTM B117 Salt Spray Test
- Scribed ASTM B117 Salt **Spray Test**
- > G85 SO₂
- Beach Corrosion
- Hardness (Pre/Post 385F-6hrs)
- Machining Evaluation Coupons(1/2 coated) & 1/2" diameter rods (2"of 6" length)





Timeline



- Over 550 Coated Samples (JTP and Sump Qualification)
 - 6061 samples were started on July 25 and anticipated to be completed by September 1
 - HP-Al bond coat/CP-Al sprayed with N₂ should be completed by September 25
- ➤ Testing is being coordinated with Penn State, Pax River, Cherry Point, Westmoreland, L&M Machine Shop, TEC, and UTRC. December 2009 for most data!
- > Demonstration at Cherry Point by the end of 2009
- ➤ Qualification of ASB and Demonstration at their site by the end of 2009
- ➤ Possibility that DSTO, Rosebank, and the Australian Navy might sign off on the process by the end of 2009




CGT Kinetics 4000 and K-Tech System



- 47 kW system Installed 6/2008 at APG (30 kW on floor and 17kW on gun)
- Only high pressure/high temperature C.S. system currently on the market
 - Temperatures up to 800°C (1472°F)
 - Pressures up to 40 bar (580 PSI)
- > 17 kW system installation at NADEP-CP
 - Larger heat to be installed in late 2009
- Ktech System at ARL:
 - Temperature limited to 500°C
 - Pressures up to 35 bar (500 PSI)
 - 25 kW heater on floor
 - Heated powder gas feed









CGT 4000 Models



Modeled deposition efficiencies appear to be close to experimental values while the calculated velocities are well above the critical velocities for Al (~500 m/s)











Valimet 6061 Cold Spray on 6061 Substrate: Optical Microscopy











100X




Valimet 6061 Cold Spray on 6061 Substrate: Optical Microscopy



Before Etching


10-20 Seconds Kroll's Etch





Valimet H-12 CP-Al Cold Spray on 6061 Substrate: Optical Microscopy







Technical Progress: Preliminary Kinetics 4000 data




- ➤ Improved D.E. from 34% to over 60% as compared to the K-Tech
- Adhesion values similar to K-Tech (10 KSI for CP-AI)
- ➤ Coating Densities >98.5% Theoretical Density for CP-Al with N₂

>99.3% for 6061AA with He



CP-Al Cold Spray Coatings entered Salt Fog on 3/4/09 ((~1/2 yr.)





6061 Cold Spray Coatings entered Salt Fog on 3/9/09 (~1/2 yr.)



CP-Al Hardness









Bond Bar Adhesion (ASTM






All Samples failed within the adhesive and not at the coating/substrate interface


| | Alloy | Average (ksi) | Stdev (ksi) | 95% Confidence (ksi) |
|---|----------|------------------|----------------|----------------------------|
| | ZE41A-T5 | 11.1 | 0.8 | 10.5, 11.6 |
| | AZ91C-T6 | 10.8 | 1.1 | 9.9, 11.6 |
|) | EV31-T6 | 11.2 | 0.7 | 10.8, 11.7 |

ZE41A-T5

AZ91C-T6

EV31-T6







CP-Al Preliminary ESTCP Data and DSTO Data show 10 ksi+



6061 Triple Lug Shear








| Alloy | Average (ksi) | Stdev (ksi) | 95% Confidence (ksi) |
|----------|------------------|----------------|----------------------------|
| ZE41A-T5 | 20.4 | 0.8 | 19.9, 20.8 |
| AZ91C-T6 | 19.0 | 2.5 | 17.5, 20.5 |
| EV31-T6 | 22.1 | 2.8 | 20.5, 23.7 |


- AZ91C-T6 and EV31-T6 failed with a relatively clean break at coating the interface
- 7 out of 12 ZE41A-T5 samples failed within the Mg





RCB Cold Spray Set-Up








RDECOM Fatigue from DSTO Project



Fatigue Results – ZE41A-T5






Fatigue from DSTO Project



Fatigue Results – AA7075-T651




Source - Australian Defense Science & Technology Organization




Overview of 2008/Early 2009 Technical Progress: DSTO





Interior section of Intermediate Gearbox (IGB)



Exterior corroded area on one of the as-received IGB pads



Overview of 2008/Early 2009 Technical Progress: DSTO



Interior section of IGB pads coated with CP-aluminum






Pre-Cold Spray

CP Al Cold Spray



Overview of 2008/Early 2009 Technical Progress: DSTO






CP Al Cold Spray





UH-60 Sump Assembly Main Module -Main Gearbox Repair








RDECOM UH-60 Sump Assembly Main Module -Main Gearbox Repair






Cold Spray Repair of Inside Diameter of **Flange**



RDECOM UH-60 Sump Assembly Main Module -Main Gearbox Repair









Summary



Cold Spray offers a cost effective and environmentally friendly method for repair and corrosion protection of Mg Components

Hardness

```
ZE41A Magnesium alloy = 68 Vickers
Cold Spray CP-AI = 63 Vickers
6061=105 Vickers
```

Bond Strength

```
>6061 has >10,000 psi on ZE41, AZ91, and EV31 (CGT)
```

>6061 surpassed 15,000 PSI for Triple Lug Shear

>CP-AI/HP-AI has >=10,000 psi on ZE41 and AZ91 (K-Tech and CGT)

RCB Fatigue Strength

Minimal effect on both 7075-T6 and ZE41A Magnesium Alloy

Salt Fog Corrosion

>4000 hrs on CGT (on going) and 6000+ hrs for K-Tech